

Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

# **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

## SECTION 1: Identification of the substance/mixture and of the company/undertaking

#### 1.1 Product identifier

Trade name : METALURE L-51007 MA

Material number : 020573IA0

### 1.2 Relevant identified uses of the substance or mixture and uses advised against

This information is not available.

#### 1.3 Details of the supplier of the safety data sheet

Company : ECKART GmbH

Guentersthal 4 91235 Hartenstein

Telephone : +499152770 Telefax : +499152777008

E-mail address : msds.eckart@altana.com

Responsible/issuing person

#### 1.4 Emergency telephone number

### NCEC:

(contract no.: ECKART29003-NCEC)

+44 1235 239671 (Middle East/Africa, call and response in your language)

+1 215 207 0061 (Americas, call and response in your language)

+65 3158 1074 (Asia-Pacific, call and response in your language)

### **SECTION 2: Hazards identification**

#### **GHS Classification**

: Flammable liquids, Category 3, H226

Specific target organ toxicity - single exposure, Category 3,

Central nervous system, H336

Page 1 / 20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

## **GHS-Labelling**

Symbol(s) :





Signal word : Warning

Hazard statements : H226: Flammable liquid and vapour.

H336: May cause drowsiness or dizziness.

Precautionary statements : **Prevention:** 

P210 Keep away from heat, hot surfaces, sparks, open

flames and other ignition sources. No smoking.

P233 Keep container tightly closed.

P240 Ground and bond container and receiving equipment.
P241 Use explosion-proof electrical/ventilating/lighting

equipment.

P242 Use non-sparking tools.

P243 Take action to prevent static discharges.

P261 Avoid breathing mist or vapours.

P271 Use only outdoors or in a well-ventilated area.

P280 Wear protective gloves/ protective clothing/ eye

protection/ face protection/ hearing protection.

Response:

P303 + P361 + P353 IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse affected areas

with water.

P304 + P340 + P319 IF INHALED: Remove person to fresh air and keep comfortable for breathing. Get medical help if you

feel unwell.

P370 + P378 In case of fire: Use dry sand, dry chemical or

alcohol-resistant foam to extinguish.

Storage:

P403 + P233 Store in a well-ventilated place. Keep container

tightly closed.

P403 + P235 Store in a well-ventilated place. Keep cool.



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

P405 Store locked up.

Disposal:

P501 Dispose of contents/ container to an approved waste

disposal plant.

## Hazardous components which must be listed on the label

Identification CAS-No. 2-methoxy-1-methylethyl acetate 108-65-6 acetone 67-64-1

## **SECTION 3: Composition/information on ingredients**

Substance No. :

## **Hazardous components**

Chemical name	CAS-No. EINECS-No.	Classification and labelling	Concentration[%]
2-methoxy-1-methylethyl acetate	108-65-6 203-603-9	Flam. Liq.;3;H226 STOT SE;3;H336	50 - 100
aluminium	7429-90-5 231-072-3	Flam. Sol.;1;H228	10 - 20
acetone	67-64-1 200-662-2	Flam. Liq.;2;H225 Acute Tox.;5;H303 Acute Tox.;5;H313 Eye Dam./Irrit.;2A;H319 STOT SE;3;H336	1 - 10

For the full text of the H-Statements mentioned in this Section, see Section 16.

Page 3 / 20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

#### **SECTION 4: First aid measures**

## 4.1 Description of first aid measures

General advice : Move the victim to fresh air.

Move out of dangerous area.

Show this safety data sheet to the doctor in attendance.

If inhaled : Consult a physician after significant exposure.

If unconscious, place in recovery position and seek medical

advice.

In case of skin contact : Wash off immediately with soap and plenty of water.

If on skin, rinse well with water. If on clothes, remove clothes.

In case of eye contact : Immediately flush eye(s) with plenty of water.

Flush eyes with water as a precaution.

Remove contact lenses.

Keep eye wide open while rinsing.

If swallowed : Keep respiratory tract clear.

Do not give milk or alcoholic beverages.

Never give anything by mouth to an unconscious person.

If symptoms persist, call a physician.

#### 4.2 Most important symptoms and effects, both acute and delayed

This information is not available.

### 4.3 Indication of any immediate medical attention and special treatment needed

This information is not available.

### **SECTION 5: Firefighting measures**

### 5.1 Extinguishing media

Suitable extinguishing media : Dry sand, ABC powder, Foam

Unsuitable extinguishing

media

: High volume water jet, Carbon dioxide (CO2)

Page 4 / 20 102000000681 A member of C ALT	TANA
--	------



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

#### 5.2 Special hazards arising from the substance or mixture

Specific hazards during

firefighting

: Do not allow run-off from fire fighting to enter drains or water

courses.

5.3 Advice for firefighters

Special protective equipment

for firefighters

: Wear self-contained breathing apparatus for firefighting if

necessary.

Further information : Collect contaminated fire extinguishing water separately. This

must not be discharged into drains. Fire residues and

contaminated fire extinguishing water must be disposed of in accordance with local regulations. For safety reasons in case

of fire, cans should be stored separately in closed

containments.

#### **SECTION 6: Accidental release measures**

## 6.1 Personal precautions, protective equipment and emergency procedures

Personal precautions : Evacuate personnel to safe areas.

Remove all sources of ignition. Evacuate personnel to safe areas.

Beware of vapours accumulating to form explosive concentrations. Vapours can accumulate in low areas.

#### 6.2 Environmental precautions

General advice : The product should not be allowed to enter drains, water

courses or the soil.

Prevent product from entering drains.

Prevent further leakage or spillage if safe to do so.

If the product contaminates rivers and lakes or drains inform

respective authorities.

This information is not available.

## 6.3 Methods and materials for containment and cleaning up

Page 5 / 20 102000000681 A member of ALTA	.TANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

Methods for cleaning up : Use mechanical handling equipment.

Soak up with inert absorbent material (e.g. sand, silica gel,

acid binder, universal binder, sawdust).

Contain spillage, and then collect with non-combustible absorbent material, (e.g. sand, earth, diatomaceous earth, vermiculite) and place in container for disposal according to

local / national regulations (see section 13).

Do not flush with water.

#### 6.4 Reference to other sections

For personal protection see section 8.

## **SECTION 7: Handling and storage**

## 7.1 Precautions for safe handling

Advice on safe handling : Avoid formation of aerosol. Do not breathe vapours/dust.

Avoid exposure - obtain special instructions before use. For personal protection see section 8. Smoking, eating and drinking should be prohibited in the application area. Take precautionary measures against static discharges. Provide sufficient air exchange and/or exhaust in work rooms. Open drum carefully as content may be under pressure. Dispose of rinse water in accordance with local and national regulations.

Advice on protection against

fire and explosion

Do not spray on a naked flame or any incandescent material. Take necessary action to avoid static electricity discharge (which might cause ignition of organic vapours). Keep away from open flames, hot surfaces and sources of ignition.

Hygiene measures : Wash hands before breaks and at the end of workday.

## 7.2 Conditions for safe storage, including any incompatibilities

Requirements for storage areas and containers

: Earthing of containers and apparatuses is essential. Reaction with water liberates extremely flammable gas (hydrogen) Take measures to prevent the build up of electrostatic charge. Use explosion-proof equipment. Store in original container. Keep containers tightly closed in a cool, well-ventilated place. Keep

Page 6 / 20	10200000681	A member of <b>ALTANA</b>
-------------	-------------	---------------------------



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

# **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

away from sources of ignition - No smoking. Keep container closed when not in use.

No smoking. Keep container tightly closed in a dry and well-ventilated place. Containers which are opened must be carefully resealed and kept upright to prevent leakage. Electrical installations / working materials must comply with

the technological safety standards.

Further information on storage conditions

: Protect from humidity and water.

Advice on common storage : Do not st

: Do not store near acids. Do not store together with oxidizing and self-igniting products. Never allow product to get in contact with water during storage. Keep away from oxidizing agents, strongly alkaline and strongly acid materials in order to

avoid exothermic reactions.

Other data : No decomposition if stored and applied as directed.

## 7.3 Specific end use(s)

This information is not available.

## **SECTION 8: Exposure controls/personal protection**

#### 8.1 Control parameters

#### Germany:

Components	CAS-No.	Value type (Form of exposure)	Control parameters	Update	Basis
2-methoxy-1- methylethyl acetate	108-65-6	TWA	50 ppm 275 mg/m3	2000-06-16	2000/39/EC
Further information	Further information Identifies the possibility of significant uptake through the		n the		

Page 7 / 20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

# **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

		skinIndicative			
2-methoxy-1- methylethyl acetate	108-65-6	STEL	100 ppm 550 mg/m3	2000-06-16	2000/39/EC
Further information		Identifies the possibility of significant uptake through the skinIndicative			
2-methoxy-1- methylethyl acetate	108-65-6	AGW	50 ppm 270 mg/m3	2006-01-01	DE TRGS 900
Peak-limit: exc factor (categor		1;(I)			
Further information		place dangerous Union (The EU I and peak limit a	sion for the review s for the health (MA has established a lire possible)When to ical tolerance value	AK-commission) imit value: devia there is compliar	European tions in value nce with the
aluminium	7429-90-5	AGW (Inhalable fraction)	10 mg/m3	2021-07-02	DE TRGS 900
Peak-limit: excursion factor (category)		2;(II)			
Further inform	ation	When there is compliance with the OEL and biological tolerance values, there is no risk of harming the unborn child			
aluminium	7429-90-5	AGW (Alveolate fraction)	1,25 mg/m3	2021-07-02	DE TRGS 900
Peak-limit: exc factor (categor		2;(II)			
Further inform	ation	When there is compliance with the OEL and biological tolerance values, there is no risk of harming the unborn child			
acetone	67-64-1	TWA	500 ppm 1 210 mg/m3	2000-06-16	2000/39/EC
Further inform	ation	Indicative			
acetone	67-64-1	AGW	500 ppm 1 200 mg/m3	2015-03-02	DE TRGS 900
Peak-limit: exc factor (categor		2;(I)			

Page 8 / 20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

# **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

Further information	Commission for dangerous substances Senate commission for the review of compounds at the work place dangerous for the health (MAK-commission). European Union (The EU has established a
	limit value: deviations in value and peak limit are possible)When there is compliance with the OEL and biological tolerance values, there is no risk of harming the unborn child

## United States of America (USA):

Components	CAS-No.	Value type (Form of exposure)	Control parameters	Update	Basis
2-methoxy-1- methylethyl acetate	108-65-6	TWA	50 ppm	2008-01-01	
2-methoxy-1- methylethyl acetate	108-65-6	PEL	100 ppm 541 mg/m3	2014-11-26	
2-methoxy-1- methylethyl acetate	108-65-6	STEL	150 ppm 811 mg/m3	2014-11-26	
aluminium	7429-90-5	TWA (total dust)	50 Million particles per cubic foot	2012-07-01	
aluminium	7429-90-5	TWA (Respirable)	5 mg/m3	2013-10-08	
aluminium	7429-90-5	TWA (total dust)	15 mg/m3	2012-07-01	
aluminium	7429-90-5	TWA (total)	10 mg/m3	2013-10-08	
aluminium	7429-90-5	TWA (respirable fraction)	5 mg/m3	2012-07-01	
aluminium	7429-90-5	TWA (respirable fraction)	15 Million particles per cubic foot	2012-07-01	
aluminium	7429-90-5	PEL (Total dust)	10 mg/m3	2014-11-26	
aluminium	7429-90-5	PEL (respirable dust fraction)	5 mg/m3	2014-11-26	
aluminium	7429-90-5	TWA (Respirable particulate matter)	1 mg/m3	2008-01-01	
aluminium	7429-90-5	TWA	5 mg/m3	2005-09-01	
aluminium	7429-90-5	TWA (Total)	15 mg/m3	1989-01-19	

Page 9 / 20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

# **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

aluminium	7429-90-5	TWA (Respirable fraction)	5 mg/m3	1989-01-19	
aluminium	7429-90-5	TWA (total dust)	15 mg/m3	2011-07-01	
aluminium	7429-90-5	TWA (respirable fraction)	5 mg/m3	2011-07-01	
aluminium	7429-90-5	TWA (Total dust)	15 mg/m3	1989-01-19	
aluminium	7429-90-5	TWA (respirable dust fraction)	5 mg/m3	1989-01-19	
aluminium	7429-90-5	TWA (welding fumes)	5 mg/m3	2013-10-08	
aluminium	7429-90-5	TWA (pyro powders)	5 mg/m3	2013-10-08	
aluminium	7429-90-5	TWA (Respirable particulate matter)	1 mg/m3	2013-03-01	
aluminium	7429-90-5	TWA (Fumes)	5 mg/m3	1989-01-19	
aluminium	7429-90-5	PEL (Welding fumes)	5 mg/m3	2017-10-02	
aluminium	7429-90-5	PEL (Pyro powders)	5 mg/m3	2017-10-02	
aluminium	7429-90-5	TWA (powder)	5 mg/m3	1989-01-19	
acetone	67-64-1	TWA	250 ppm	2016-03-01	
acetone	67-64-1	STEL	500 ppm	2016-03-01	
acetone	67-64-1	TWA	250 ppm 590 mg/m3	2013-10-08	
acetone	67-64-1	TWA	1 000 ppm 2 400 mg/m3	1997-08-04	
acetone	67-64-1	TWA	750 ppm 1 800 mg/m3	1989-01-19	
acetone	67-64-1	STEL	1 000 ppm 2 400 mg/m3	1989-01-19	
acetone	67-64-1	STEL	750 ppm 1 780 mg/m3	2014-11-26	
acetone	67-64-1	С	3 000 ppm	2014-11-26	
acetone	67-64-1	PEL	500 ppm 1 200 mg/m3	2014-11-26	

A member of C ALTANA	Page 10 / 20	10200000681	A member of <b>C</b> ALTANA
----------------------	--------------	-------------	-----------------------------



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

### 8.2 Exposure controls

#### Personal protective equipment

Eye protection : Goggles

Safety glasses

Hand protection

Material : Solvent-resistant gloves (butyl-rubber)

Remarks : Take note of the information given by the producer concerning

permeability and break through times, and of special

workplace conditions (mechanical strain, duration of contact). The exact break through time can be obtained from the protective glove producer and this has to be observed.

Please observe the instructions regarding permeability and breakthrough time which are provided by the supplier of the gloves. Also take into consideration the specific local conditions under which the product is used, such as the

danger of cuts, abrasion, and the contact time. Recommended preventive skin protection

Skin should be washed after contact.

The suitability for a specific workplace should be discussed

with the producers of the protective gloves.

: The suitability for a specific workplace should be discussed

with the producers of the protective gloves.

Skin and body protection : Choose body protection according to the amount and

concentration of the dangerous substance at the work place.

Respiratory protection : Use suitable breathing protection if workplace concentration

requires.

: In the case of vapour formation use a respirator with an

approved filter.

#### **Environmental exposure controls**

General advice : The product should not be allowed to enter drains, water

courses or the soil.

Page 11 / 20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

Prevent product from entering drains.
 Prevent further leakage or spillage if safe to do so.
 If the product contaminates rivers and lakes or drains inform respective authorities.

## **SECTION 9: Physical and chemical properties**

#### 9.1 Information on basic physical and chemical properties

Appearance : liquid

Colour : silver

Odour : characteristic

pH : substance/mixture is non-soluble (in water)

Freezing point : No data available

Boiling point/boiling range : 146  $^{\circ}$ C Flash point : 46  $^{\circ}$ C

Bulk density : No data available
Flammability (solid, gas) : No data available
Auto-flammability : No data available
Upper explosion limit : No data available
Lower explosion limit : No data available
Vapour pressure : No data available
Density : 0,9 g/cm3 (20 °C)

Solubility(ies)

Water solubility : insoluble

Miscibility with water : immiscible

Solubility in other solvents : No data available

Page 12 / 20	10200000681	A member of <b>C</b> ALTANA
		I I TO THE SHOP IN THE SECOND SH



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

Partition coefficient: n-octanol/water : No data available Ignition temperature : No data available Thermal decomposition : No data available Viscosity, dynamic : No data available Viscosity, kinematic : No data available Flow time : No data available

#### 9.2 Other information

No data available

## **SECTION 10: Stability and reactivity**

#### 10.1 Reactivity

No decomposition if stored and applied as directed.

## 10.2 Chemical stability

No decomposition if stored and applied as directed.

## 10.3 Possibility of hazardous reactions

Hazardous reactions : Contact with acids and alkalis may release hydrogen.

Stable under recommended storage conditions.

Vapours may form explosive mixture with air.

10.4 Conditions to avoid

Conditions to avoid : Do not allow evaporation to dryness.

Heat, flames and sparks.

10.5 Incompatible materials

Materials to avoid : Acids

Bases

Oxidizing agents

Page 13 / 20	10200000681	A member of <b>C</b> ALTANA
	1	



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

### 10.6 Hazardous decomposition products

Other information : No data available

## **SECTION 11: Toxicological information**

## 11.1 Information on toxicological effects

**Acute toxicity** 

### **Components:**

acetone:

Acute oral toxicity : LD50 Rabbit: 4700 - 5 800 mg/kg

Mouse: 3 000 mg/kg

Rat: 9 800 mg/kg

Acute inhalation toxicity : LC50 Rat: 76 mg/l

Exposure time: 4 h

Test atmosphere: vapour

Acute dermal toxicity : LD50 Rabbit: > 2 000 mg/kg

#### Skin corrosion/irritation

No data available

Page 14/20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

### Serious eye damage/eye irritation

No data available

### Respiratory or skin sensitisation

No data available

### Carcinogenicity

No data available

## Toxicity to reproduction/fertility

No data available

## Reprod.Tox./Development/Teratogenicity

No data available

### STOT - single exposure

No data available

#### STOT - repeated exposure

No data available

## Aspiration toxicity

No data available

### **Further information**

### **Product**

Symptoms of overexposure may be headache, dizziness, tiredness, nausea and vomiting., Concentrations substantially above the TLV value may cause narcotic effects., Solvents may degrease the skin.

Page 15 / 20	10200000681	A member of <b>C</b> ALTANA



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

## **SECTION 12: Ecological information**

### 12.1 Toxicity

## **Components:**

acetone (67-64-1):

Toxicity to daphnia and other : (Daphnia magna (Water flea)): 21 600 mg/l

aquatic invertebrates

## 12.2 Persistence and degradability

No data available

## 12.3 Bioaccumulative potential

No data available

### 12.4 Mobility in soil

No data available

### 12.5 Results of PBT and vPvB assessment

No data available

#### 12.6 Other adverse effects

## **Product:**

Additional ecological

information

: No data available

Page 16 / 20 102000000681	A member of <b>O ALTANA</b>
---------------------------	-----------------------------



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

## **SECTION 13: Disposal considerations**

#### 13.1 Waste treatment methods

Product : Do not dispose of waste into sewer.

Do not contaminate ponds, waterways or ditches with

chemical or used container.

Send to a licensed waste management company. In accordance with local and national regulations.

Contaminated packaging : Empty remaining contents.

Dispose of as unused product. Do not re-use empty containers.

Do not burn, or use a cutting torch on, the empty drum. In accordance with local and national regulations.

## **SECTION 14: Transport information**

#### 14.1 UN number

ADR : 1263
TDG : 1263
CFR : 1263
IMDG : 1263
IATA : 1263

### 14.2 Proper shipping name

ADR : PAINT
TDG : PAINT
CFR : PAINT
IMDG : PAINT
IATA : PAINT

#### 14.3 Transport hazard class

Page 17 / 20 102000000681 A member of <b>()</b> ALTAN	Page 17 / 20
---	--------------



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

ADR : 3
TDG : 3
CFR : 3
IMDG : 3
IATA : 3

## 14.4 Packing group

### **ADR**

Packaging group : III

Classification Code : F1

Hazard Identification Number : 30

Labels : 3

Tunnel restriction code : (D/E)

**TDG** 

Packaging group : III Labels : 3

**CFR** 

Packaging group : III Labels : 3

**IMDG** 

Packaging group : III Labels : 3

EmS Code : F-E, <u>S-E</u>

IATA

Packing instruction (cargo

aircraft)

Packing instruction

(passenger aircraft)

: 366

: 355

Page 18 / 20	102000000681	A member of <b>C ALTANA</b>



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

## **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

Packing instruction (LQ) : Y344 Packaging group : 111 Labels : 3

#### 14.5 Environmental hazards

#### 14.6 Special precautions for user

## 14.7 Transport in bulk according to Annex II of MARPOL 73/78 and the IBC Code

No data available

## **SECTION 15: Regulatory information**

### 15.1 Safety, health and environmental regulations/legislation specific for the substance or mixture

REACH - Candidate List of Substances of Very High

Concern for Authorisation (Article 59).

REACH - List of substances subject to authorisation

(Annex XIV)

Regulation (EC) No 1005/2009 on substances that

deplete the ozone layer

Regulation (EU) 2019/1021 on persistent organic

pollutants (recast)

Regulation (EU) 2019/1148 on the marketing and use of

explosives precursors

REACH - Restrictions on the manufacture, placing on

the market and use of certain dangerous substances,

mixtures and articles (Annex XVII)

REACH - Restrictions on the manufacture, placing on

the market and use of certain dangerous substances.

mixtures and articles (Annex XVII)

: Not applicable

: Not applicable

: Not applicable

: Not applicable

: Listed

(acetone)

: Banned and/or restricted

(2-methoxy-1-methylethyl acetate) (aluminium powder (stabilised))

(acetone)

Page 19 / 20 102000000681	A member of <b>C</b> ALTANA
---------------------------	-----------------------------



Globally Harmonized System of Classification and Labelling of Chemicals (GHS)

# **METALURE L-51007 MA**

Version 4.0 Revision Date 09.01.2025 Print Date 14.01.2025

### 15.2 Chemical safety assessment

No data available

### **SECTION 16: Other information**

#### Full text of H-Statements

H225 : Highly flammable liquid and vapour. H226 : Flammable liquid and vapour.

H228 : Flammable solid.

H303 : May be harmful if swallowed.

H313 : May be harmful in contact with skin. H319 : Causes serious eye irritation. H336 : May cause drowsiness or dizziness.

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.